

WESTCHESTER TOWNSHIP MUSEUM

WINDOW REHABILITATION

Window / Door Schedule
Westchester Township History Museum

Mark Description

- 1 East Elevation - First Floor - restore per section 086.10
- 2 East Elevation - First Floor - part of a double window - restore per section 086.10
- 3 East Elevation - First Floor - part of a double window - restore per section 086.10
- 4 East Elevation - First Floor - restore per section 086.10
- 5 East Elevation - First Floor - restore per section 086.10
- 6 East Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 7 East Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 8 East Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- B-1 East Elevation - Basement - restore per section 086.10
- B-2 East Elevation - Basement - restore per section 086.10
- 9 South Elevation - First Floor - restore per section 086.10
- 10 South Elevation - First Floor - restore per section 086.10
- 11 South Elevation - First Floor - restore per section 086.10
- 12 South Elevation - First Floor - restore per section 086.10
- 13 South Elevation - First Floor - restore per section 086.10 - note storm sash bottom rail requires replacement
- 14 West Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 15 West Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 16 West Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 17 West Elevation - First Floor - a more recent window - remove storm and clean storm and window - prep and paint window surround/trim
- 18 West Elevation - First Floor - restore per section 086.10
- 19 West Elevation - First Floor - restore per section 086.10
- 20 West Elevation - First Floor - restore per section 086.10
- 21 West Elevation - First Floor - restore per section 086.10
- 22 North Elevation - First Floor - restore per section 086.10
- 23 North Elevation - First Floor - restore per section 086.10
- 24 East Elevation - Second Floor - restore per section 086.10
- 25 East Elevation - Second Floor - restore per section 086.10
- 26 East Elevation - Second Floor - restore per section 086.10
- 27 East Elevation - Second Floor - half round fixed window restore per section 086.10 - no storm window
- 28 South Elevation - Second Floor - restore per section 086.10
- 29 South Elevation - Second Floor - restore per section 086.10
- 30 South Elevation - Second Floor - pair of French wood storm doors - restore per section 086.10, clean and do not paint hardware
- 31 South Elevation - Second Floor - restore per section 086.10
- 32 South Elevation - Second Floor - restore per section 086.10
- 33 South Elevation - Second Floor - restore per section 086.10
- 34 West Elevation - Second Floor - half round fixed window restore per section 086.10 - no storm window
- 35 West Elevation - Second Floor - restore per section 086.10
- 36 West Elevation - Second Floor - restore per section 086.10
- 37 North Elevation - Second Floor - restore per section 086.10
- 38 North Elevation - Second Floor - restore per section 086.10
- 39 East Elevation - Attic Level - triangular multi-lite window - restore per section 086.10
- 40 West Elevation - Third Floor - set of three windows with transoms and decorative molding / surrounds - restore per section 086.10 - carefully evaluate and document deterioration at roof joint and restore / replace damaged materials
- 41 West Elevation - Attic Level - triangular multi-lite window - restore per section 086.10
- 42 North Elevation - Third Floor - shed dormer with three windows - restore per section 086.10 - carefully evaluate and document deterioration at roof joint and restore / replace damaged materials

Doors

- A East Elevation - First Floor - remove storm door, clean, sand, prep and paint storm door, door, frame, and trim
- B East Elevation - First Floor - more recent steel door, clean, sand, prep and paint door, frame, and trim
- C East Elevation - Third Floor - French Door to sleeping balcony - restore similar to section 086.10 Note: Balcony railing and decorative brackets will require new infill for missing historic trim, repair, and then preparation for paint
- D South Elevation - First Floor - remove storm doors, clean, sand prep and paint and re-install, sand prep and paint doors, frame, and trim
- E North Elevation - First Floor -clean, sand, prep, and paint door, frame and trim, carefully examine base of door / trim and threshold and repair and restore damaged materials

SHEET INDEX

- A2.0 COVER SHEET AND SCHEDULE
- A2.1 EAST ELEVATION NOTES
- A2.2 SOUTH ELEVATION NOTES
- A2.3 WEST ELEVATION NOTES
- A2.4 NORTH ELEVATION NOTES



THIS IS AN ORIGINAL DESIGN, CREATED BY SRKM ARCHITECTURE, INC. IT IS SUBMITTED FOR USE IN THE PROJECT AND IS UNDER THE DOMINION AND CONTROL OF THE ARCHITECT. ANY OTHER USE OR REPRODUCTION OF THIS INFORMATION WITHOUT THE WRITTEN CONSENT OF SRKM ARCHITECTURE, INC. IS PROHIBITED. SRKM ARCHITECTURE, INC. 120 SOUTH BURNING WOODS, INDIANAPOLIS, IN 46260

REVISION:

COVER SHEET AND SCHEDULE
WESTCHESTER TOWNSHIP MUSEUM
700 W PORTER, CHESTERTON, IN

PROJECT No.	2015-031
DRAWN BY:	DDB
CHECKED BY:	JLK/BAM
DATE	SEPTEMBER 2015
SHEET No.	A2.0

SRKM architecture
120 SOUTH BURNING WOODS, INDIANAPOLIS, IN 46260 PHONE 317.428.1156 WWW.SRKMARCH.COM